



HELPFUL RESOURCES

- [Using Milestone Decals PDF](#)
- [TipSheet 4: Designing Your Own Art Glass](#)

PRODUCTS FEATURED IN THIS LESSON

- [Fusible Decals, Black](#)
- [Fusible Decals, Blue](#)
- [Fusible Decals, Copper](#)
- [Fusible Decals, Gold](#)
- [Fusible Decals, Platinum](#)
- [Fusible Decals, White](#)
- [Crystal Clear Transparent, Powder Frit \(1401-0008\)](#)
- [Bullseye Shelf Primer, 5 lb bucket \(8220\)](#)
- [Disposable Particulate Respirator N95, 20 pack \(8262\)](#)

ADDITIONAL SUPPLIES & EQUIPMENT IN THIS LESSON

- Scissors
- Tub of distilled water
- Lint-free towels
- Sifter
- Spatula

FIRING SCHEDULE

FULL FUZE

	RATE	TEMPERATURE	HOLD
1	80° F (26° C)	185° F (85° C)	:20
2	175° F (79° C)	400° F (204° C)	:15
3	200° F (93° C)	600° F (315° C)	:15
4	1000° F (538° C)	1240–1370° F (743° C)	:10
5	AFAP	900° F (482° C)	1:00
6	100° F (38° C)	700° F (371° C)	:00
7	AFAP	70° F (21° C)	:00